


ACERA Rapidfire Plus Lever
ST-M3050 (3x9-speed)



ITEM NO.	SHIMANO CODE NO.	DESCRIPTION	INTERCHANGE-ABILITY		
1	Y8MK98010	R.H. Lid Unit			
	Y8MJ98010	L.H. Lid Unit			
2	Y8MK03000	R.H. Lid			
	Y8MJ53000	L.H. Lid			
3	Y8V108000	R.H. Diaphragm	A		
	Y8V108010	L.H. Diaphragm	A		
4	Y8V198030	Bleed Screw (M5 x 4.6) & O-Ring	A		
5	Y6PZ98070	Shifting Cable Adjusting Bolt Unit	A		
6	Y6CD33000	Inner Hole Cap	A		
7	Y8MK98020	Main Lever Cover & Fixing Screw (M2.5 x 5.2)	A		
8	Y8AF02000	Clamp Bolt (M6 x 19.5)	A		
9	ESMDISCBP	Funnel & Oil Stopper	A		

A: Same parts.

B: Parts are usable, but differ in materials, appearance, finish, size, etc.

Absence of mark indicates non-interchangeability.

Specifications are subject to change without notice.

Mar.-2015-3842

© Shimano Inc. I

SHIMANO